

Annexure D

BYUILDING SAFETY CERTIFICATE

No.

Date:

It is certified that the existing building **SHRI TUNGAL INTERNATIONAL SCHOOL** (name of the building or premises) at Sy No. 18/6 of Kanamadi Village, Tq: Tikota, Dist: Vijayapur (address) is having block (s)/Floor (s) as per details below:

Details of block (s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No.of Floor (s) in the Block	01 Block with 3 floors (Ground Floor, First Floor & Second Floor)	-	-	-	-	-

The building is owned/occupied by **Shri Gajanan Education and Rural Development Association (R), Kanamadi** (name of the institution) have complied with the building safety requirements in accordance with National building code Rules, and verified by the officers concerned of **PUBLIC WORKS DEPARTMENT OF KARNATAKA (PWD)** on **02.06.2026** (date of inspection) in the presence of **Shri Vinit K, Head Master of Tungal International School** and that the building/ premises is fit for occupancy for running school with effect from **18.05.2026** for a period of **01** years in accordance with rule and subject to compliance of the specific conditions as appended.

1. NIL

2. NIL

3. NIL

4. NIL

Issued on **18.05.2026** at office of PWD SUB DIVISION VIJAYAPUR by,

*Strike out whichever is not applicable. In case of block is more than six use separate sheet for details.

Signature with Seal: _____

Name: _____

Designation: **Assistant Executive Engineer,**
Public Works Department,
Sub Division, VIJAYAPUR

Section officer

Name & Address of Department Office: _____